



**Keystone RV
Company**

**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: 19V-596
Safety Advisory: 19-358
Transport Canada: 2019-406
October 2, 2019

Recall Population

2020 Crossroads Cruiser Fifth Wheels

Models: 29SI, 27MK, 28RD, 24RL, 29RK

Serial Number Range:

L6320022 - L6320115

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided that the vehicles in the recall population have a Morryde Rotating Pin Box and may have been manufactured with improper length bolts that hold the wedge to the pin box. If the Rotating Pin Box is unlocked and allowed to rotate and the wedge is installed with improper length bolts, the wedge may become disconnected from the pin box. This would allow the rotating pin box to pivot in two places which could allow the trailer to come in contact with the truck. This could increase the risk of a crash.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to inspect bolts in the wedge plate of each pin box and replace as needed. The service and parts required for this corrective action will be provided at no charge to you.

***What we
need you to
do***

As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)



**PO Box 2000 – Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com**